

SERVICE MANUAL

Correction

Full Panel Detachable
High Power
FM / AM Stereo Receiver
Compact Disc Player

ECD-780

114782838

Regarding ECD-780, the wrong drawing has appeared in CD mechanism exploded view. Please see the CD mechanism exploded view in this Supplement and use this together with the original Service Manual (Ref. No. SM-7900004) that had already been issued to refer for the slight amendment of the design.

CD Mechanism Exploded View (MECHANISM #5BB002)

